

**In the Specification**

Please replace the text beginning on page 6, lines 2429 of the specification with the following paragraph:

End walls 18, 20 also include an alignment area having two generally horizontal and parallel rib members 84 defining a space 86 therebetween. When assembled, alignment member 60 of the receiver is disposed between parallel rib members 84 80,82. The latch striker area includes a generally vertical member 98 (Figure 2) disposed in an assembled orientation between striker 72 and the interior surface of side walls 14,16 for enhancing lateral retention between adjacent walls.